



CYLINDRICAL FAST ACTING FUSES - SCREWING TYPES


Fusing Characteristics




Current-Limiting Characteristics




Temperature Rise



Power Loss



Shutdown I²t Against Working AC Voltage



Application to Direct-Current Circuit

